



HFPJC · אבותינו

אבותינו

וועד הפועל להצלת קברי ישראל באיראפּע

Heritage Foundation for Preservation of Jewish Cemeteries (HFPJC)

616 Bedford Ave. #2-B · Brooklyn, NY 11249 · Tel: 718-640-1470 · Fax: 718-228-8368 · Email: hfpjc@thejnet.com

A NON PROFIT ORGANIZATION

## ASSESSMENT REPORT

ת"ס

Date of Evaluation: 10/6/2022  
 Requested by: Mr. Menachem Moshe Retek  
 Location: Brooklyn, NY  
 Cemetery Name: Szerencs  
 Alternative Name/s: \_\_\_\_\_  
 Yiddish Name: סערענטש  
 Location: Arpad ut. 1  
 GPS (DMS): \_\_\_\_\_  
 GPS (DD): \_\_\_\_\_  
 Country: Hungary

Cemetery size rate:	Linear meters
Size A	Up to 150m
Size B	150-300m
Size C	300- 450m
Size D	450-600m
Size E	600m and up

### DESCRIPTION OF ENCLOSURE

Fence Not Present

Fence Present

North     South     East     West

Fence Height: 1.8

Fence material:  Brick     Concrete     Metal     Wire

Other Desc: Stone

Fence Condition:  Satisfactory     Unsatisfactory

Fence Description: Stone

Notes

### DESCRIPTION OF INTERIOR

Condition Of Grounds: Fair to poor

Condition Of Gravestones: Very poor

Ohel

Description: Poor

Amount of Gravestones Visible: 400

### CONTACT INFORMATION

Contact person present at time of Evaluation:

Caretaker: \_\_\_\_\_

Address: \_\_\_\_\_

Result Of Dialogue: \_\_\_\_\_

Problems:

זכות המצוה הגדולה, יגן לכל העוזרים ומסייעים, להתברך בכל מעשי ידיהם, והקדושים אשר בארץ המה יליצו יושר בעדיהם אכי"ר.

In the tremendous merit of honoring the deceased, may you and yours be blessed with bountiful success. Amen.



HFPJC · אבותינו

אבותינו

וועד הפועל להצלת קברי ישראל באיראפּע

Heritage Foundation for Preservation of Jewish Cemeteries (HFPJC)

616 Bedford Ave. #2-B · Brooklyn, NY 11249 · Tel: 718-640-1470 · Fax: 718-228-8368 · Email: hfpjc@thejnet.com

A NON PROFIT ORGANIZATION

## ASSESSMENT REPORT

ט"ס

The stone fence surrounding the cemetery is built on clay. If it gets wet (the visor gets damaged, for instance) it will collapse. Therefore we have to pay special attention to make sure that the visor is in perfect condition. (correct dripcap visor, and good gasket). Due to the temperature changes, the concrete stretches and shrinks which could cause it to crack; therefore there have to be gaps in the concrete, filled with flexible material that can stretch and shrink as needed thereby preventing the development of cracks in the wall.

Note: This Report is a rough estimate generated by the initial evaluation. details may change as project draws closer

זכות המצוה הגדולה, יגן לכל העוזרים ומסייעים, להתברך בכל מעשי ידיהם, והקדושים אשר בארץ המה יליצו יושר בעדיהם אכי"ר.

In the tremendous merit of honoring the deceased, may you and yours be blessed with bountiful success. Amen.