אבותינו

וועד הפועל להצלת קברי ישראל באייראפע



Heritage Foundation for Preservation of Jewish Cemeteries (HFPJC)

616 Bedford Ave. #2-B · Brooklyn, NY 11249 · Tel: 718-640-1470 · Fax: 718-228-8368 · Email: hfpjc@thejnet.com

A NON PROFIT ORGANIZATION ASSESSMENT REPORT

ב0״ד

Date of Evaluation: 11/2/2011	Cemetery size rate: Linear mete		
Requested by: Mr. Moishe Lazer Rubinstein			
Location: Brooklyn, NY	Size A Up to 150m Size B 150-300m		
Cemetery Name: Romuli	Size C 300- 450m		
Alternative Name/s: Rumoli	Size D 450-600m		
Yiddish Name: סטרימבא	Size E 600m and up		
Location:			
GPS (DMS): 47°32'9.54"N 24°25'47.61"E	_		
GPS (DD)	_		
Country: Romania			
DESCRIPTION OF ENCLOSURE	DESCRIPTION OF INTERIOR		
E Fence Not Present	Condition Of Grounds: Fairly bad		
	Condition Of Gravestones: Bad condition		
✓ Fence Present	Ohel		

✓ North	South	✓ East	✓ West	
Fence Height:				
Fence material:	□ Brick	Concrete	🗌 Metal	✓ Wire
Other Des	SC:			
Fence Condition	n: 🗌 Sat	isfacory	✓ Unsatisfacto	ry
Fence Desciption	n:			

i	Condition Of Grounds:	Fairly Dau		
	Condition Of Gravestones:	Bad condition		
	□ Ohel			
	Description:			
	Amount of Gravestones Visible:	60		
	CONTACT INFORMATION			
	Contact person present at time of Evaluation:			
	Caretaker:			
	Address:			
	Result Of Dialogue:			

Notes

Problems:

One side of the Bais Hachaim is very hilly, and another side is next to a road. When building the fence it has to be made very stable, maybe widen the road or build a retainer wall

Note: This Report is a rough estimate generated by the initial evaluation. details may change as project draws closer

זכות המצוה הגדולה, יגן לכל העוזרים ומסייעים, להתברך בכל מעשי ידיהם, והקדושים אשר בארץ המה יליצו יושר בעדיהם אכי"ר.

In the tremendous merit of honoring the deceased, may you and yours be blessed with bountiful success. Amen.

Affiliated Organizations: London: Committee for Preservation of Jewish Cemeteries in Europe · E. Israel: Asra Kadisha